



BONDERITE C-AK 4215 NC-LT AERO ALKALINE CLEANER (KNOWN AS TURCO 4215 NC-LT)

Issuedd 3/18/2019

DESCRIPTION:

BONDERITE C-AK 4215 NC-LT AERO (known as TURCO 4215 NC-LT) is a white granular mix developed for cleaning ferrous and nonferrous alloys by spray, immersion and ultrasonic methods at low temperatures.

BONDERITE C-AK 4215 NC-LT AERO (known as TURCO 4215 NC-LT) is ideal for cleaning fuel and hydraulic components and for cleaning metals prior to metal bonding.

BONDERITE C-AK 4215 NC-LT AERO (known as TURCO 4215 NC-LT) contains a balanced blend of organic surface-active agents designed to control any tendencies to foam, even under conditions of severe agitation. A characteristic of this designed foam control is that, at elevated temperatures (above about 40°C), one of the surface active agents will become less soluble, separate and float to the top of the cleaning solution. This is a normal operating characteristic of this product. The oily-looking layer that floats on top of the solution at operating temperature, is then, one of the active ingredients and should not be skimmed.

BONDERITE C-AK 4215 NC-LT AERO (known as TURCO 4215 NC-LT) is not recommended for use on magnesium alloys.

FEATURES:

BONDERITE C-AK 4215 NC-LT AERO (known as TURCO 4215 NC-LT) offers these features:

- I. Noncorrosive to aluminum, steel, copper and plated metals
- II. Readily soluble in water
- III. Nonfoaming at recommended concentrations and temperatures
- IV. Readily rinses from metals
- V. Free of harsh caustics

USE INSTRUCTIONS:

Tanks: Tanks, headers and associated equipment may be fabricated from mild or stainless steel.

Spray Systems: Add BONDERITE C-AK 4215 NC-LT AERO (known as TURCO 4215 NC-LT) to cold water at the ratio of 7 to 15 g/liter of water. Operate tank from 45°-55°C, for 2 to 4 minutes. Rinse with cold to warm water.

Immersion Systems: Add BONDERITE C-AK 4215 NC-LT AERO (known as TURCO 4215 NC-LT) to cold water at the ratio of 45 to 60 g/liter of water. Use air or mechanical agitation. Operate tank from 45°-55°C for 5 to 10 minutes. Rinse with cold to warm water by spray or overflowing immersion methods.

Ultrasonic Systems: Add BONDERITE C-AK 4215 NC-LT AERO (known as TURCO 4215 NC-LT) at the ratio of 4 to 15 g/liter of water. Degas system prior to cleaning. Rinse with cold to warm water.





BONDERITE C-AK 4215 NC-LT AERO ALKALINE CLEANER (KNOWN AS TURCO 4215 NC-LT)

CONTROL:

ALKALINITY (Informational Only):

APPARATUS:

- I. 592495 - Pipet, 25 mL
- II. 592488 – flask, Erlenmeyer, 250 mL
- III. 592477 - Buret, 25 mL
- IV. pH Meter (optional)

REAGENTS:

- I. Sulfuric Acid, 1.0000 N (normal) standardized
- II. 594088 - Indicator 2 (Bromocresol Green)

PROCEDURE:

- I. Obtain a sample of process solution and allow it to cool to room temperature.
- II. Pipet a 50 mL sample into a 250 mL Erlenmeyer Flask.
- III. Add 5-8 drops of Indicator 2.
- IV. Titrate with 1.0 N sulfuric acid until the color changes from blue-green
- V. To yellow. If a pH meter is available, titrate to pH 4.0.
- VI. Record the milliliters of 1.0 N sulfuric acid used.

CALCULATIONS:

Milliliters of 1.0 N sulfuric Acid x 0.533 = oz/gallon BONDERITE C-AK 4215 NC-LT AERO (known as TURCO 4215 NC-LT)

SOLUTION MAINTENANCE:

Maintain the bath concentration within the recommended range by adding fresh material.

Recommended Concentrations:

- Spray System: 7.5-15 gm/L (1-2 oz/gallon)
- Immersion System: 45-60 gm/L (6-8 oz/gallon)
- Ultrasonic System: 4-15 gm/L (0.5-2 oz/gallon)

Concentration of BONDERITE C-AK 4215 NC-LT AERO (known as TURCO 4215 NC-LT) by Surfactant Titration:

APPARATUS:

1. 595344 –Pipet, 10 ml
2. Flask, Volumetric, 100ml
3. Buret, 50 mL
4. Flask, Erlenmeyer, 250 mL



BONDERITE C-AK 4215 NC-LT AERO ALKALINE CLEANER (KNOWN AS TURCO 4215 NC-LT)

REAGENTS:

1. 592451 - Titration Solution 45
2. 593969 - Auxiliary Test Solution 76
3. 592415 - Indicator 99

PROCEDURE:

1. Obtain a sample of process solution. Add a stir bar and mix until the sample has reached room temperature.
2. Pipet 10 mL of sample into a 100 mL volumetric flask. Make to volume with deionized water and mix. Pipet a 10 mL aliquot into a 250 mL Erlenmeyer flask.
3. Add 25 mL of deionized water, 10 drops of Indicator 99 and 5 mL of Auxiliary Test Solution 76.
4. Titrate with Titration Solution 45 to a blue endpoint (free of reddish tint)

CALCULATIONS:

$$\frac{(\text{Milliliters of Titration Solution 45} + 0.167)}{0.314} = \text{gm/L BONDERITE C-AK 4215 NC-LT AERO}$$

$$\frac{\text{gm/L BONDERITE C-AK 4215 NC-LT AERO}}{7.49} = \text{oz/gal BONDERITE C-AK 4215 NC-LT AERO}$$

DISPOSAL INFORMATION:

Dispose of spent solution per local, state and regional regulations. Refer to HENKEL MATERIAL SAFETY DATA SHEET for additional disposal information.

WARNING! Causes eye irritation. May cause skin irritation.

BONDERITE C-AK 4215 NC-LT AERO (known as TURCO 4215 NC-LT) contains borate, phosphate and silicofluoride. Avoid contact with eyes, skin and clothing. Do not take internally. Use with adequate (equivalent to outdoor) ventilation.

Protective clothing, such as a chemical face shield or goggles, gloves, boots and apron made from alkali resistant materials should be worn when handling and using this product. A NIOSH-approved respirator should be worn during dust or mist conditions.

Store in closed containers away from direct sunlight or excessive heat.

Before using this product refer to container label and HENKEL MATERIAL SAFETY DATA SHEET for additional precautionary, handling and first aid information.





BONDERITE C-AK 4215 NC-LT AERO ALKALINE CLEANER (KNOWN AS TURCO 4215 NC-LT)

NOTICE:

The above information and recommendations concerning this product are based upon our laboratory tests and field use experience with this or similar products. However, since conditions of actual use are beyond our control, any recommendations or suggestions are made without warranty, express or implied. Manufacturer's and seller's sole obligation shall be to replace that portion of the product shown to be defective. Neither shall be liable for any loss, damage, or injury, direct or consequential, arising out of the use of this product.

Henkel Corporation | 32100 Stephenson Highway | Madison Heights, MI 48071
PHONE: (248) 583-9300 | FAX: (248) 583-2976 | www.henkelna.com/

Trademark usage

Except as otherwise noted, all trademarks in this document are trademarks of Henkel Corporation in the U.S. and elsewhere. ® denotes a trademark registered in the U.S. Patent and Trademark Office.

The data contained herein are furnished for information only and are believed to be reliable. We cannot assume responsibility for the results obtained by others over whose methods we have no control. It is the user's responsibility to determine suitability for the user's purpose of any production methods mentioned herein and to adopt such precautions as may be advisable for the protection of property and of persons against any hazards that may be involved in the handling and use thereof. In light of the foregoing, **Henkel Corporation specifically disclaims all warranties expressed or implied, including warranties of merchantability or fitness for a particular purpose, arising from sale or use of Henkel Corporation's products. Henkel Corporation specifically disclaims any liability for consequential or incidental damages of any kind, including lost profits.**

The discussion herein of various processes or compositions is not to be interpreted as representation that they are free from domination of patents owned by others or as a license under any Henkel Corporation patents that may cover such processes or compositions. We recommend that each prospective user test his proposed application before repetitive use, using this data as a guide. This product may be covered by one or more United States or foreign patents or patent applications.

